



Manufacturer	OKUMA
Model	MILLAC44V
Task	Disk spring replacement

Overview of repair machines :Disk spring replacement】





[Disc springs and their arrangement]...\*

Total:2 days

[Implementation details and approximate man-hours]

- Pay attention to the orientation and combination of the disc springs.
- The depth of the cylinder must be measured accurately with a depth meter of some kind. Otherwise, the tapping allowance will change.
- The clamp allowance should be 0.7 to 0.8mm

If you only need to replace the plate spring ;

works;2 days

\* [Key points of the exchange operation : Accurately measure the depth of the cylinder to which the disc spring is mounted, and check the mounting accuracy and clamping allowance.]







[Appearance after removal of disc spring]

【Confirmation of clamping allowance】

[Accurately record depth for reassembly]

[ Overview of replacement works ]

Preliminary inspection and preparation

Tomminary independent and proparation			
	Works		
Check the clamping force. (Clamping force measuring instrument should be prepared by the customer.)		Factors causing additional	
	• If you only need to replace the dish spring, it can	items	
	be done in two days.	• Damage or replacement of parts other than those assumed will be quoted separately.	
		-	