

HIOZAWA NEWS


Manufacturer HAKUSAN KOUSAKUSYO

Den

Repair & overhaul of turret

[Overview of repair machines]





[There is a 0.3 mm steps on the swivel of the swivel base of the turret section.]

[Implementation details and approximate man-hours]

- Additional machining (grinding) is also available.
- The overall accuracy is checked, and the surface is scraped to ensure that it is in a state of accuracy.

Man-hours for grinding process and repair when parts are available.

Grinding;0.5 days

Total:2 days

* [Key points of the exchange operation : If the wear is so excessive that it cannot be corrected by the kisage (Scraping) process, a grind process can be performed.]







[Scraping of the feed table

[Correction of steps by [Wear condition of the tool post feed grinding] table section]

Overview of maintenance works

Preliminary inspection and preparation

works

 Replacement of parts such as feed screws requires confirmation of the supply system on the part of the manufacturer

. Gibs can be manufactured in-house, but delivery time depends on the availability of drawings. Grinding process can be done in 0.5 days if the schedule can be arranged.

◆ If the grinding process can be done in 0.5 days, 2 days are required, including the grinding process.

Factors causing additional items

slide section

If turcite is affixed to the gib, a separate delivery date is required. An additional 3 days is required to make a turciteattached gib.

• If there are no drawings of the gib, delivery time will be required to measure and create the gib from the actual one.